RESUBDIVISION OF PART OF NEW ALBANY COUNTRY CLUB SECTION 21 RICHMOND SQUARE

Situated in the State of Ohio, County of Franklin, City of New Albany, and in Quarter Township 3, Township 2, Range 16, United States Military Lands, containing 1.051 acres of land, more or less, said 1.051 acres being a resubdivision of Lots 2 through 8, both inclusive, of the subdivision entitled "New Albany Country Club Section 21 Richmond Square", of record in Plat Book 109, Pages 5 and 6, Recorder's Office, Franklin County, Ohio.

The undersigned, THE NEW ALBANY COMPANY LLC, a Delaware limited liability company, by BRENT B. BRADBURY, Chief Financial Officer, owner of the lands platted herein, duly authorized in the premises, does hereby certify that this plat correctly represents its "RESUBDIVISION OF PART OF NEW ALBANY COUNTRY CLUB SECTION 21 RICHMOND SQUARE", a subdivision containing Lots numbered 13 to 17, both inclusive, do hereby accept this plat of same.

Easements are hereby reserved in, over and under areas designated on this plat as "Easements are nevery reserved in, over and under areas designated or his plat as "Easement". The aforementioned designated easements permit the construction, operation and maintenance of all public and quasi-public utilities above, beneath and on the surface of the ground and, where necessary, for the construction, operation and maintenance of service connections to all adjacent lots and lands and for storm water drainage. No building shall be constructed in any area over which easements are hereby reserved.

In Witness Whereof, BRENT B. BRADBURY, Chief Financial Officer of THE NEW ALBANY COMPANY, LLC, has hereunto set his hand this ______ day of C-______ day of C-______ day of

THE NEW ALBANY COMPANY, LLC ed and Acknowledged Phyllin Poakin

STATE OF OHIO COUNTY OF FRANKLIN ss:

BRADBURY Chief Financial Of MELISSA D. BICKFORD

NOTARY PUBLIC, STATE OF GRID

Before me, a Notary Public in and for said State, personally appeared BRENT B. BRADBURY, Chief Financial Officer of THE NEW ALBANY COMPANY, LLC, who acknowledged the signing of the foregoing instrument to be his voluntary act and deed and the voluntary act and deed of said THE NEW ALBANY COMPANY, LLC for the uses and purposes expressed herein.

In Witness Thereof, I have hereunto set my hand and affixed my official seal this day of **Ostroly**, 2013.

My commission expires 5/17/17 Musice D. Bicklock

Approved this <u>1</u>st Day of <u>**Ret**</u> 2013

Approved this Day of OCT

Approved this <u></u>Day of <u>Oct</u>

Approved this 7 Day of dCT

Approved this 15^{+} Day of $0c^{+}$ 2013

Approved and accepted by Resolution No. R-37-2013 passed 9-17-, 2013, as such, by the Council for the City of New Albany, Ohio. Approval of this plat shall become null and void unless recorded prior to 47-9-17-, 2014.

Transferred this 16 day of Oct. 2013.

Filed for record this 16 day of <u>0ct.</u>, 2013 at 10:43 <u>AM. Fee \$ 172.50</u>


File No. 2013 10/ 601 74 962


Recorded this 16 day of 9ct 20 13.


Plat Book 116 , Pages 49 - 50

. .










Franklin County, Ohio


Franklin County, Ohio



Deputy Recorder, Franklin County, Ohio

Matthew Swain

PLAT BOOK 116 PG 49



LOCATION MAP AND BACKGROUND DRAWING SCALE: 1" = 1000'

SURVEY DATA:

BASIS OF BEARINGS: The bearings shown hereon are based on the same meridian as the bearings shown neteon are subdivision plat entitled "New Albany Country Club Section 19" of record in Plat Book 101, Pages 21 and 22, Recorders Office, Franklin County Ohio. On said plat of record a portion of the centerline of Ogden Woods Boulevard has a bearing of North 04°19'12" East.

SOURCE OF DATA: The sources of recorded survey data are the records of the Franklin County, Ohio, Recorder, referenced in the plan and text of this plat.

IRON PINS, where indicated hereon, unless otherwise noted, are to be set and are iron pipes, thirteen-sixteenths inch inside diameter, thirty inches long with a plastic plug placed in the top end bearing the initials EMHT INC.

PERMANENT MARKERS: Permanent markers, where indicated hereon, are to be one-inch diameter, thirty-inch long, solid iron pins, are to be set to monument the points indicated and are to be set with the top end flush with the surface of the ground and then capped with an aluminum cap stamped EMHT INC. Once installed, the top of the cap shall be marked (punched) to record the actual location of the point. These markers shall be set following the completion of the construction/installation of the street pavement and utilities and prior to the City of New Albany, Ohio's acceptance of these subdivision improvements. The New Albany, Ohio, Municipal Engineer shall be notified when the markers are in nlace.



We do hereby certify that we have surveyed the above premises, prepared the attached plat, and that said plat is correct. All dimensions are in feet and decimal parts thereof.

o = Iron Pin (See Survey Data) • = MAG Nail to be set

Matthe a Uk

◎ = Permanent Marker (See Survey Data)

Professional Surveyor No. 7865




New Albany Company / Resubdivision of Part of New Albany Country Club Section 21 / 2010-0630 / 20100630FP

OCT B

Date





4. 1

NOTE "A" - No determination has been made by the City of New Albany, Ohio as to whether the area proposed to be platted contains area(s) that could be classified as Wetlands by the Army Corps of Engineers. It is the developer's responsibility to determine whether Wetlands exist on the area hereburghted. hereby platted. The City of New Albany, Ohio, approval of this final plat of Resubdivision of part of New Albany Country Club Section 21 Richmond Square does not imply any approval of the site as it may pertain to Wetlands.

PLAT BOOK 116 PG 50

2

NOTE "B" - All of the area hereby platted is within Zone X (area determined to be outside of the 0.2% annual chance floodplain) as shown on Federal Emergency Management Agency Flood Insurance Rate Map for Franklin, County, Ohio and Incorporated Areas, map numbered 39049C0204 K with effective date of June 17, 2008.

NOTE "C" - DEPRESSED DRIVEWAYS: Depressed driveways are hereby prohibited on all lots in the Resubdivison of part of New Albany Country Club Section 21 Richmond Square subdivision. Nothing herein, however, shall prohibit the construction and use of, if otherwise permitted, a driveway alongside or to the rear of a residential structure.

NOTE "D": At the time of platting, electric, cable, and telephone service providers have not issued information required so that easement areas, in addition to those shown on required so that easement areas, in addition to mose shown on this plat as deemed necessary by these providers for the installation and maintenance of all of their main line facilities, could conveniently be shown on this plat. Existing recorded easement information about Resubdivision of part of New Albany Country Club Section 21 Richmond Square or any part thereof can be acquired by a competent examination of the then current public records, including those in the Recorder's Office Frenklin Country Ohio Office, Franklin County, Ohio.

NOTE "K" - ACREAGE	E BRI	EAKI	DOV	VN:	
Total acreage				,	1.051 Ac.
Acreage in Lots	- 1	÷.,		1.1.1	1.051 Ac.
Acreage in Right-of-way			۰.		0.000 Ac.

NOTE "L" - ACREAGE BREAKDOWN: "Resubdivision of part of New Albany Country Club Section 21 Richmond Square" is comprised of the following Franklin County Parcel Numbers:

222-003932		1		0.163 Ac	•
222-003931				0.141 Ac	•
222-003930	÷* .			0.156 Ac	•
222-003929				0.140 Ac	
222-003928		1	· ·	0.150 Ac	•
222-003927			, ·	0.151 Ac	•
222-003926				0.150 Ac	•
				,	

		CUR	VE TABLE	······	
CURVE NO.	DELTA	RADIUS	LENGTH	CHORD BEARING	CHORD DISTANCE
CI	90'00'00"	20.00	31.42	N 821418 E	28.28
C2	90'00'00"	10.00'	15.71	S 07*45'42* E	14,14
C3	21'04'22	200.49'	73.74	S 26'42'07" W	73.32
C4	11 48 34	200.49'	41.32	S 1015'39" W	41.25
C5	14'01'41	410.00'	100.38	S 11 22 06 W	100.13
C6	9"59'30"	410.00'	71.50	S 23'22'41" W	71,41
C7	94'16'02"	35.00'	57.58	S 75'30'27" W	51.31'
C8	86'43'27"	10.00'	15.14	N 13'59'48" W	13.73
Cġ	11'01'16"	375.00'	72.13	N 23'51'18" E	72.02'
C10	12"23"08"	375.00'	81.06	N 12'09'06" E	80.91
CII	15 42 37	275.00'	75.40	N 1210'19" E	75,17
C12	171241	275.00'	82.61	N 28'37'58" E	82.30
C13	1'38'20	375.00'	10.73	N 05'08'22" E	10.73

New Albany Company / Resubdivision of Part of New Albany Country Club Section 21 / 2010-0630 / 20100630FP1